


REVISIONS

REV.	DESCRIPTION	DATE	APPROVED
B	Change to 4 bolts on bushin block, remove top carriage3 bolts replace with K.O.	8/30/2024	DC
C	Change 1603-226 to 1601-246, Replace upper spacer 2601-134 with 1601-032 Bushing	1/1/2026	DC



Notes: Unless Otherwise Specified.

