

Wiring Instructions for 1812-035 24 Volt DC 570mA Power Transformer Assembly

Some power transformers may come supplied with a plug-in connector attached to the end of the supply line. If this is the case, remove the connector by cutting it off from the end of the supply wires.

This is a DC Transformer. Polarity must be observed!

The solid black wire is <u>NEGATIVE</u>.

The wire with the white stripe is <u>POSITIVE</u>.

