

REVISIONS

REV.	DESCRIPTION	DATE	APPROVED
A	Created new operator 1603-380 from old number 1603-180	6/9/2021	DC
B	Change to 4 bolts on bushing block, remove top carriage bolts replace with K.O.	8/30/2024	DC





